



FIG. 1











DEC 1 3 2004

## 10/042,771 Inventor: Stuart Hall Method & Apparatus for Displaying Help Screen Information for Measurement Device









8/10





FIG. 3C








FIG. 5A




FIG. 5B




FIG. 5C